

Industry : measures related to the handling of machines

Material is constantly used on the industrial site. It is important to ensure the work is organised in such a way that the exchange of materials is kept to a minimum.

Some guidelines about the handling of machines

- Reorganise the work so the number of employees using the same material is limited.
 - Each operator is to be given their own machine, the machine must only be operated by 1 operator.
 - Provide a maximum of 1 person per aerial platform, and preferably always the same person for the same machine. If several aerial work platforms are being used, observe the social distancing rules (1.5 m) between the aerial work platforms and persons involved.
- If it is still necessary to swap: clean or disinfect the surfaces that are touched frequently
 - Always remove and clean key after use
 - Clean the radio control daily
 - Clean handles of shared material (use disinfectant cleaning cloths if necessary)
- Everyone is to use their own safety harness, PPE must never be exchanged.
- Limit the number of people per activity and preferably only swap with 1 person. This will ensure social distancing is guaranteed.
- Personal tools: everyone is to use their own tools as much as possible.
- If someone falls ill, all tools with which the sick employee came into contact are to be disinfected.
- Do not exchange cell phones, walkie-talkies, headsets, etc.
- Avoid passing building materials to each other.

This document was prepared on 27 April 2020 on the basis of the measures in force on that date